

Vector Frame Light Box R-07

VF-LB-R-07

Vector Frame™ fabric light boxes feature durable 100mm aluminum extrusion frames, push-fit back-lit fabric graphics and LED top and bottom lighting. Single and double-sided graphic options are available. LED lights come adhered to the frame, making set-up as simple as assembling the frame, applying the push-fit graphics and plugging in the electrical cord!



features and benefits:

- 100mm (4") silver extrusion frame
- Integrated LED lighting strips top & bottom
- Single or double-sided SEG dye-sublimated push-fit fabric graphics
- Easy assembly
- Comes packaged with two OCH wheeled molded case for transport and storage
- Lifetime hardware warranty against manufacturer defects

dimensions:

Hardware	Graphic
Assembled unit: 236.5" w x 94.7" h x 19.7" d 6006mm(w) x 2405mm(h) x 500mm(d) Approximate weight: 190 lbs / 86 kgs	Refer to related graphic template for more information. Visit: www.exhibitors-handbook.com/graphic-templates
Shipping	
Packing case(s): 2 OCH Shipping dimensions: 50" l x 29" w x 12" h 1270mm(l) x 737mm(h) x 305mm(d) Approximate total shipping weight (includes cases & graphics): 244 lbs / 111 kgs	additional information: Graphic material: dye-sublimation fabric Power requirements: 24V / 3.0A / 72 watts per transformer Two transformers per unit When included in larger kit, a different packaging solution will be listed to accommodate all contents of the kit. Individual packaging no longer provided

We are continually improving and modifying our product range and reserve the right to vary the specifications without prior notice. All dimensions and weights quoted are approximate and we accept no responsibility for variance. E&OE. See Graphic Templates for graphic bleed specifications.

Included In Your Kit


Tools, Components, & Connectors



5MM ALLEN-T x1



CB9 x4




IB2 x14



SW-FOOT-500-LN x2



LED-WHT-DB-300 x36



LED-DB-PWRSUPPLY x4



LED-DB-PWRCORD x4



LED-DB-CL-DCJ-600 x4




LED-DB-CL-2400 x4




LN114-S2-450-TT x1

Graphics




VF-LB-R-07-S-G x1



VF-LB-R-07-OP-LN x1

Included In Your Kit

Extrusions



WME-1000 x4



PHFC4-1200-L1-L1 x6



PHFC4-1200-L1-MCB9 x6



PHFC4-1200-L1-MCB9-GR x2




AF16-300-MCB4-MCB4-SIDE x2



PH-1155-L1-S x8

Exploded View


VF-LB-R-07



Back View

Internal Lighting Setup

VF-LB-R-07




Back View

Connection Methods

Extrusion based structures use a number of different yet simple connection methods. Your kit will include one or more of the connection methods shown below. Steps within the Kit Assembly will reference a specific method for each connection point.


Connection Method 1: Cam Lock / Slide Lock



A cam lock equipped extrusion can lock to any cam lock channel. With the cam lock unlocked, set the teeth of the cam lock into the desired position on the cam lock channel. Using your allen key tool, carefully turn the lock clockwise to lock in place. Be sure to lock securely, but do not over tighten.

A slide lock equipped extrusion can also lock into any cam lock channel. When the slide lock is unlocked, pull back on the hex bolt head to retract the slide lock into the body of the extrusion. Slide locking procedure is the same as a cam lock.

Connection Method 2: IB2 / Corner Brackets



Press the hex bolt head in with your thumb and slide the extrusion and connector together so that the hex bolt head sits into the lock hole. Repeat with the second extrusion to the free end of the connector. Lock the extrusions together by turning carefully with the allen key tool. Be sure to lock securely, but do not over tighten.

Connection Method 3: SW-FOOT




An SW-FOOT assembly consists of two thumb screws, an LN100, and SW-FOOT baseplate. Start by loosening the thumb screws (it is best not to completely remove the screws). Slide the extrusion onto the LN100 by utilizing its back cam channel. When the extrusion rests on baseplate or ground (depending on application), tighten the thumb screws to lock in place. Do not over tighten.

LN114-S2

Connection Methods

Extrusion based structures use a number of different yet simple connection methods. Your kit will include one or more of the connection methods shown below. Steps within the Kit Assembly will reference a specific method for each connection point.

Connection Method 4: Internal Lighting Setup



Be sure to fully assemble all frames before using the internal lighting components. With the thumbscrews loosened, place the light strips on the frame, then hand tighten them in series, male to female connections with extension cords. Do not over tighten the thumbscrews. Snap on the wire management extrusions with the power cord extensions in place. Reference the Internal Lighting Diagram for more details.



Kit Assembly

Step by Step


Step 1.

Gather the components necessary for assembling your light box frame. Assemble in the order the Exploded View instructs. Connect the AF16's on the middle channel for single sided graphics and on the farthest back channel for double sided graphics.

Refer to Connection Methods 1 and 2 for additional information.



Single Sided Graphic with Opaque Liner





Double Sided Graphic

Step 2.


Gather the components necessary for the Internal Lighting assembly to your light box. Assemble in the order the Exploded View and the Internal Lighting Setup Diagram instructs.

Refer to Connection Method 4 for additional information.




Step 3.

Locate your silicone edge fabric panels. Push the silicone edges of the graphic panel into the primary grooves of the PHFC4 extrusion perimeter. Push the silicone edges of the opaque liner into the secondary grooves of the PHFC4 extrusion perimeter.



Single Sided Graphic with Opaque Liner



Double Sided Graphic

Step 4.

Gather the components necessary for assembling your frame stabilizing bases. Assemble in the order the Exploded View instructs.

Refer to Connection Method 3 for additional information.

Setup Complete.

